

Lieutenant Governor

## State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

## **Minerals Inspection Report**

Reviewed

	Repor	rt Date: 08/28/2013	3		
Mine Name: Quarry		Permit Number:	S/023/0096	Mine Status:	Active
Operator Name: Cox Transportation Incorporated		Inspection Date:	08/14/2013	Permit Fees:	Paid
Inspector(s): Wayne Western		Inspection Time:	12:05 -	Bond Amount:	\$13,000
Attendee(s):		Weather:	80's fair sky	Bond Escalation:	08/09/2017
Insp	ection Purpose: Routine inspection			Prior Inspection:	08/28/2012
Con	clusions and Recommendations				
Elements of Inspection				Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds					
	The bond and permit fees are up to date. The BLM determine what mining activities can occur on the s		site. The Divisi	on will coordinate with th	e BLM to
2.	Public Safety (shafts, adits, trash, signs, highwalls)				
3.	Protection of Drainages/Erosion Control				
4.	Deleterious Material				
5.	Roads (maintenance, surfacing, dust control, safety	)			
6.	Reclamation				
	The Operator is reclaiming the site as part of the mi consists of removing stockpiles of gypsum.	ning operations. Basically	the site was dis	sturbed long ago and the m	nining operation
	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)				
7.	Backfilling/Grading (trenches, pits, roads, nighwan	Soils			
7. 8.					


Inspector's	Signature:
-------------	------------

 $File: \ /O/M023-Juab/S0230096-CoxTransportation/inspections/Insp08142013.pdf$ 







Loadout areas



Loadout are and stockpiles



Stockpiles and working area



Terrace areas that were pre-law and outside the permit area.

